

## Division of Water Resources 1-888-891-8332 (TDEC)

## General NPDES Permit for Stormwater Discharges from Industrial Activities (TMSP)

## Sector J - Summary

You now have Tennessee Multi-Sector Stormwater Permit (TMSP) coverage. Here's what to do next:

- 1. Keep the **Notice of Coverage (NOC)** on-site (*Section 4.2.2 of the TMSP*)
- 2. Make sure that the **Storm Water Pollution Prevention Plan** (SWPPP) is signed (*Section 4.2.1 of the TMSP*), kept on-site, and contains at a minimum the following information (*Section 3 of Sector J*):
  - List of the pollution prevention team members;
  - Drainage map showing outfalls and directions of stormwater runoff;
  - Description of potential pollutant sources at the facility; and
  - Description of ways to prevent pollution of stormwater
- 3. Conduct inspections, make notes, and keep inspection notes on-site:
  - ✓ **Quarterly** during dry weather, check structural controls and Best Management Practices (BMPs) (Section 3.2.3.4 of Sector J);
  - ✓ **Quarterly** when it rains, check BMPs and all outfalls for signs of pollution (*Sections 3.2.3.4 and 5.3 of Sector J*); and
  - ✓ **Annually** during dry weather, check entire site and all outfalls (Section 3.2.4 of Sector J):
    - Write a report describing any problems noted during inspection
- 4. Conduct sampling (*Table in Section 1 of Sector J*):
  - ✓ **Quarterly** during wet weather, collect stormwater samples from the outfall(s) and have them analyzed by a lab (*Section 5 of Sector J*; for facilities with SIC 1422, 1423, 1429, 1442, and 1446, refer to Section 4 and Section 5 of Sector J):
    - What to sample for? Check tables with parameters in Section 5 (for facilities with SIC 1422, 1423, 1429, 1442, and 1446 refer to Section 4 and Section 5);
    - Use Annual Storm Water Monitoring Report (for facilities with SIC 1422, 1423, 1429, 1442, and 1446, use both Annual Storm Water Monitoring Report and Discharge Monitoring Report). Submit results to the Mining Section in Knoxville within 30 days of receiving results from the lab, but no later than March 31<sup>st</sup> of the following calendar year, whichever comes first (*Section 5.2 of Sector J*). If exceedances occur, please follow additional requirements of the permit (*Section 5.1.2 of Sector J and report instructions*); and
    - Keep copy of the lab results and the report you submitted (Section 7.14.2 of the TMSP)

**Note:** Some streams in Tennessee are polluted. Information regarding polluted streams can be obtained at <a href="http://tnmap.tn.gov/wpc/">http://tnmap.tn.gov/wpc/</a>. If your facility discharges a pollutant that matches a pollutant found in the receiving stream, we'll let you know on the Notice of Coverage – additional requirements may apply (Sections 1.2.3 and 4.6 of the TMSP).

Disclaimer: This document is strictly an outline of TMSP permit requirements and is not intended to replace the TMSP and specific sector documents. The permittee is obligated to comply with all terms and conditions outlined in the permit, found here: <a href="http://state.tn.us/environment/permits/tmsp.shtml">http://state.tn.us/environment/permits/tmsp.shtml</a>.