Attn: Lab Director, Lab Supervisor, Lab Personnel CLIA REQUIREMENT — THE 6 PROCEDURES OF COMPETENCY ASSESSMENT

(Moderate or High Complexity)

Must document the following:

- 1. OBSERVE routine patient test performance;
- 2. MONITOR the recording and reporting of test results;
- 3. REVIEW worksheets, quality control records, proficiency testing results, and preventative maintenance records;
- 4. OBSERVE performance of instrument maintenance and function checks;
- **5. ASSESS** the test performance of previously analyzed samples, internal blind samples or PT samples; and
- 6. ASSESS problem solving skills.

Who is required to have documented competency assessments?

Clinical Consultants (CC), Technical Consultants (TC), Technical Supervisors (TS), General Supervisors (GS) and Testing Personnel (TP), if they perform patient testing.



For a free brochure, visit: http://tn.gov/health/article/clia-formsand-resources

