Public Record Summary Information on Underground Storage Tanks (USTs) From 10/1/2022 To 9/30/2023 General Information

Total Number of Active UST Facilities: 5,142 Total Number of Active UST Tanks: 16,017

Summary Information for On-Site Inspections

Number of UST Facilities Inspected: 2,128 Inspection Period: 10/1/2022 To 9/30/2023

Percent Compliance

Spill Prevention 79.68%

Overfill Prevention 65.87%

Corrosion Protection 77.83%

Release Detection 49.72%

Technical Compliance Rate 34.08%

Note: Tanks, facility, and on-site inspection information is based on underground storage tanks regulated under Subtitle I that satisfy the definition of UST in 40 CFR 280.12, except for those tanks identified in 40 CFR 280.10(b) as excluded USTs. On-site inspections measure compliance with release detection and release prevention (significant operational compliance (SOC)/technical compliance rate (TCR), state regulations, Subtitle I, etc.).

Summary Information for Releases

Number of Confirmed UST Releases: 106 Release Reporting Period: 10/1/2022 To 9/30/2023

Summary Information for Release Sources and Causes

| | Cause | | | | | | | | | | | | | | | |
|-----------------|-------|--------|-------|---|----------|---|---------------------|-------|-----------|---|---------------------|---|-------|-------|---------|-------|
| Source/Location | | | Spill | | Overfill | | Phys/Mech Damage | | Corrosion | | Install Problems | | Other | | unknown | |
| | # | % | # | % | # | % | # | % | # | % | # | % | # | % | # | % |
| | 6 | 5.66 | | | | | 3 | 50.00 | | | | | | | 3 | 50.00 |
| | 7 | 6.60 | | | | | 1 | 14.29 | | | | | 1 | 14.29 | 5 | 71.43 |
| | 2 | 1.89 | | | | | 1 | 50.00 | | | | | | | 1 | 50.00 |
| | | 0.00 | | | | | | | | | | | | | | |
| Delivery | | | | | | | | | | | | | | | | |
| Problem | | 0.00 | | | | | | | | | | | | | | |
| | | 0.00 | | | | | | | | | | | | | | |
| | 91 | 85.85 | | | | | | | | | | | 1 | 1.10 | 90 | 98.90 |
| | 106 | 100.00 | | | | | 5 | 4.72 | | | | | 2 | 1.89 | 99 | 93.40 |

= number % = percent of total number

Note: Release, source and cause information is based on underground storage tanks regulated under subtitle I that satisfy the definition of UST in 40 CFR 280.12. This report reflects data from releases reported to the department during the time period of the report. Source and cause data were collected using on-site inspections and reports from facilities.

Additional information on site-specific USTs, such as compliance or releases may be obtained through contacting the Tennessee Division of Underground Storage Tanks at 615-532-0945.