25 Struck by falling tree limb – Inspection #1185048

A **70** year old male employee was fatally injured when he was struck by a falling tree limb during brush removal. There were no witnesses to the incident. Physical evidence and interviews imply that the victim was using a tractor to push tree limbs and debris from a path before trying to push over a standing tree with the front bucket of a tractor. The victim likely moved vines that were supporting a tree causing a limb to break and fall. The victim was fatally struck in the head and torso by the falling limb. During the investigation, it was determined that a hazard assessment was not conducted prior to the operation, appropriate personal protective equipment was not provided, and training was not provided for safe vegetation removal.

Violation(s) as Originally Issued

A complete inspection was conducted at the accident scene. Some of the items cited may not directly relate to the fatality.

Violation 1 Item 1

29 CFR 1910.132(d)(1)	The employer did not assess the workplace to determine if hazards were present, or likely to be present, which necessitate the use of personal protective equipment. On 10/12/16, the employer had failed to conduct a workplace
	assessment to adequately identify the precautions and personal protective equipment (PPE) required for employees who operated a backhoe tractor to clear fallen tree limbs and debris.

Violation 1 Item 2

29 CFR 1910.266(d)(1)(vi)	The employer did not provide, at no cost to the employee,
	and/or assure that each employee who worked in an area
	where there was potential for head injury from falling of
	flying objects wore had protection meeting the requirements
	of subpart I of Part 1910. On 10/12/16, the employer did not
	ensure that employees exposed to falling or flying objects
	wore hard hats during tree and vegetation removal operations.

Violation 1 Item 3

29 CFR 1910.266(d)(1)(vii)(A)	The employer did not provide, at no cost to the employee,
	and ensure that each employee wear eye protection meeting
	the requirements of subpart I of Part 1910 where there was
	potential for eye injury due to falling or flying objects. On
	10/12/16, the employer provided but did not ensure that each
	employee exposed to an eye injury due to falling or flying
	objects were wearing eye protection.

25 Struck by falling tree limb – Inspection #1185048

Violation 1 Item 4

29 CFR 1910.266(d)(2)(i)	The employer did not provide first-aid kits at each work site
	where trees were being cut, at each active landing, and/or on
	each employee transport vehicle. On 10/12/16, first aid kits
	were not provided at the work site where trees were being cut
	or on each employee transport vehicle.

Violation 1 Item 5

29 CFR 1910.266(f)(3)(i)	Each tractor, skidder, swing yarder, log stacker, log loader
	and mechanical felling device, such as tree shears or feller-
	buncher, place into initial service after February 9, 1995, was
	not equipped with falling object protective structure (FOPS)
	and/or rollover protective structure (ROPS). On 10/12/16,
	the KUBOTA M70 tractor being used to fell trees was not
	equipped with a falling object protective structure.

Violation 1 Item 6

29 CFR 1910.266(h)(1)(vi)	Each danger tree, including lodged trees and snags, was not
	felled or removed using mechanical or other techniques to
	minimize employee exposure before work is commenced in
	the area of the danger tree. On 10/12/16, a lodged or snagged
	tree was not felled or removed before work began in the area.

Violation 1 Item 7

29 CFR 1910.266(i)(1)	The employer did not provide training for each employee, including supervisors, at no cost to the employee. On 10/12/16, the employer had not provided annual refresher
	training to an employee who was exposed to hazardous chemicals such as carbon monoxide (CO) and gasoline fuel.

Violation 1 Item 8

TDLWD Rule 0800-01-0907	Employees were not provided annual refresher training and information as specified in TDLWD Rule 0800-01-0907 on hazardous chemicals in their work area. On 10/12/16, the
	employer had not provided annual refresher training to an employee who was exposed to hazardous chemicals such as carbon monoxide (CO) and gasoline fuel.

25 Struck by falling tree limb – Inspection #1185048



Photo 1 of 1 – Location of back-hoe tractor when victim was fatally struck by a tree limb.