A **38 year old female** security guard was crushed by a building as it collapsed on her while she sheltered in place during an EF-3 tornado at the CEVA Logistics facility.

G4S Secure Solutions Inc. provided 24 hour security at the facility. The 458,136 square feet precast concrete and steel building handled fixtures and setup materials. The building had a total of 12 employees that worked there primarily on the 1st shift.


On 3/3/2020 at approximately 1:30 am an EF-3 tornado struck the building. When the tornado hit, the victim was sheltering in place in the men's bathroom under a sink in accordance with CEVA Logistics Emergency Action Plan. The tornado collapsed the walls and roof structures.

The victim was found by emergency rescue around 11:00 am CST. It was determined that the victim was crushed by the concrete and steel of the building.

Citation(s) as Originally Issued

A complete inspection was conducted at the accident scene. Some of the items cited may not directly relate to the fatality.

No citations were recommended.



2 Crushed by building-- insp#1467240 GS4 Secure Solutions Inc.

